Sight line/Resultant Angle Square Design - Pete Galbert, Steve First Copyright (c) 2013

- Directions

  1 Draw a base line through the mortise location to it's mate on the other side of the seat pattern.

  2 Position the scale along the base line so that the splay angle contacts the mortise location.

  3 Mark the rake angle along the other leg of the scale.

  4 Connect that mark with the mortise location to make the sight line.

  5 Measure the length of the sight line with the scale to get the drilling angle.

  Visit chairnotes.blogspot.com for video instructions,

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 38